

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director MARY ANN WRIGHT Acting Division Director

Supervisor A

Inspection Report Minerals Regulatory Program Report Date: February 14, 2005

Mine Name: Windy 1 Operator or Permittee Name: Color Country Rock Permittee Mailing Address: 115 South Main Veyo, Utah 84782		number: S/6 ion Date: Fe	053/071 bruary 1, 200:	5
Inspector(s): Doug Jensen Other Participants: None	Weather: Cool, windy Inspection Start Time: 4:30 PM Inspection End Time: 5:00 PM Site location/Area Inspected (i.e. Pit #): Quarry Surface Ownership: BLM Mineral Ownership: BLM Mineral Mined: Picture Stone Type of Mine: Quarry			
Permit Status: S/053/071 Current Acreages: Total Permitted (Bonded): <5 Acres Total Disturbed: <5 Acres				
Elements of Inspection 1. Permits, Revisions, Transfer, Bonds	Evaluated	N/A	Comment	Enforcement
2. Public Safety (open shafts, adits, trash, signs, highwalls)				
3. Protection of Drainages4. Explosives, magazines5. Deleterious Material				
6. Roads (maintenance, surfacing, dust control, safety)		\boxtimes		
7. Concurrent Reclamation8. Erosion Control9. Demolition		\boxtimes		
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)				
11. Water Impoundments12. Soils13. Revegetation14. Air Quality15. Facilities				
16. Other		200		

Inspection Date: February 1, 2005; Report Date: February 14, 2005

Page 2 of 2 S/053/071

Purpose of Inspection:

I was in the area and the cable across the road was down so I decided to inspect the site. Because the access to the site has been closed, this site has not been inspected for several years.

Inspection Summary:

The quarry has not changed much since my inspection in July of 2002. A portion of the road into the site has been realigned since my last visit. The quarry does not cover a large area, total disturbance at the site including the road into the site is still less than 5 acres. Pictures were taken of the site and are included in this report.

Directions to the site:

The site is located \sim 100 feet past the Shivwitts Reservation cattle guard located on the Motaqua Road. The quarry is located on top of the ridge \sim 1 mile from the road.

GPS data:

None gathered

Inspector's Signature

_ Date: February 14, 2005


DJ:jb

Enclosures: photos

cc: Preston Hafen, Color Country Rock

Rody Cox, BLM, St George FO

O:\M053-Washington\s0530071-Windy\Inspections\02012005ins.doc





02012005 007.jpg 2005/02/01 15:02:25

02012005 008.jpg 2005/02/01 15:02:30



